POLANIK SP. Z O. O. Życzliwa 11 97-300 Piotrków Trybunalski Poland tel +48 (44) 646 44 81 tel +48 (44) 648 50 89 fax +48 (44) 646 43 58

e-mail: info@polanik.com



www.polanik.com

TECHNICAL SPECIFICATION

USER MANUAL

Mobility set for steeplechase barrier

type ZK-S0329



File: 2014-02-03 PRODUCT SUPPORT Pawel Ciechanowski <u>p.ciechanowski@polanik.comm</u>

POLANIK SP. Z O. O. Życzliwa 11 97-300 Piotrków Trybunalski Poland tel +48 (44) 646 44 81 tel +48 (44) 648 50 89 fax +48 (44) 646 43 58

e-mail: info@polanik.com



I. General use and description

Mobility set for steeplechase barrier ZK- S0329 is designed for fast and easy steeplechase barriers' transport while taking a competition or training for a steeplechase race. It is destined to transport barriers type PP-366, PP-396, PP-500. Thanks to the bearing one person is able to transport the steeplechase barrier.

II. Technical specification

Code	ZK- \$0329
construction	one-piece, steel, powder painted
wheels	4 torsional wheels, with cotter pins
height[mm]	924
bottom base[mm]	H - shaped, 300x240
upper base, Ø[mm]	round, 117
Net weight [kg]	9,50

III. Use

Step	Operation	Image
Step 1.	Operation Support one of the steeplechase barrier's ends using the bearing.	Image

tel +48 (44) 646 44 81 tel +48 (44) 648 50 89 fax +48 (44) 646 43 58



e-mail: info@polanik.com

www.polanik.com

2.	Take off the cotter pin and put the wheel's axis in a hole in a steeplechase barrier's foot. Then fasten the wheel using the cotter pin.	
3.	Repeat the described above activities to mount the second wheel.	
4.	Take off the steeplechase barrier of the bearing and support its second end(using bearing). Repeat all described above activities to mount two left wheels.	

tel +48 (44) 646 44 81 tel +48 (44) 648 50 89 fax +48 (44) 646 43 58





www.polanik.com

5.	The steeplechase	
	barrier is ready to	
	transport.	
6.	To dismount wheels use the bearing again. Take off cotter pins and put wheels' axes out. The steeplechase barrier is ready to use.	

The set is packed in foil, gross weight 10 kg.

IV. Operating and maintenance

To avoid difficulties while transporting the steeplechase barriers the surface should be even, smooth and without any obstacles. During idle periods the set should be stored in a dry, roofed place.

Even the best technical solutions cannot substitute for common sense. The usage of the product must take place under the supervision of qualified sport facilities staff. The producer shall not be liable for any incidents caused by the improper assembly or its misuse. The producer reserves the right to introduce without warning changes in product constructions and colours.